

Drives

2H042M

Fit for "11H", "14H", "16H" and "17H" Series Stepper Motors




Current/subdivision table


SW1	SW2	Subdivision
0	0	2
0	1	4
1	0	8
1	1	test

SW1	SW2	Current
0	0	0.5 Half
0	1	1.0 Half
1	0	0.5 Full
1	1	1.0 Full

Dimension



Wiring Diagram



2H057M

Fit for "17H", "23H" and "24H" Series Stepper Motors




Current/subdivision table

SW1	SW2	SW3	Subdivision
0	0	0	2
0	0	1	5
0	1	0	10
0	1	1	20
1	0	0	40


SW4, 5 keep "on",
 (SW6, 7, 8) as follows:

SW	Current	SW2	Current
000	0.5A	100	1.7A
001	1.0A	101	2.0A
010	1.3A	110	2.4A
011	1.5A	111	3.0A

Dimension



Wiring Diagram



2H090M

Fit for "23H", "24H" and "34H" Series Stepper Motors




Current/subdivision table

SW1	SW2	SW3	Subdivision
0	0	0	2
0	0	1	5
0	1	0	10
0	1	1	20
1	0	0	40

SW4, 5 keep "on",
 (SW6, 7, 8) as follows:

SW	Current	SW2	Current
000	0.5A	100	1.7A
001	1.0A	101	2.0A
010	1.3A	110	2.4A
011	1.5A	111	3.0A

Dimension



Wiring Diagram

